



Calibrazione del 05/09/2008

Sensore meccanico



$$\alpha_s = 1.55 \cdot 10^{-9} \frac{g}{n}$$

Termometro

$$\text{Temperature} = \alpha_t \cdot (\text{counts}) + b$$

$$\alpha_t = 5.65 \cdot 10^{-6} \text{ } ^\circ\text{C}/n \quad b = -30.58^\circ\text{C}$$